

# SA River Murray Flow Report



Report #07/2023

Issued 4:30 pm 17 February 2023

This supersedes the previous Flow Report issued by the Department for Environment and Water (DEW) on 10 February 2023. The next Flow Report will be provided on Friday 24 February 2023.

## Current and forecast water levels

While the peak has now passed through South Australia, flows remain elevated through the length of the River Murray in SA and the Lower Lakes. As advised previously, wind speed and direction play a significant role in daily water levels recorded in the lower section of the River Murray in SA. While a downward trend in water levels around the Lower Lakes is occurring, it remains possible that water levels may increase temporarily due to wind and tides.

The table below shows current water levels at key points along the river system and when river levels are expected to recede to below minor flood levels. River users should note that differences will be observed between the rate of rise and the rate of fall during this flood event.

Location	Normal Pool Level (m AHD)	Current level at 17/02/23 (m AHD)	Minor flood level (m AHD)	Estimated date range for river levels falling below minor flood level	Highest water level during 2022-23 flood (m AHD)
Lock 6	19.25	18.79	-	Normal pool level	21.32
Renmark Pump Stn	16.30	-	-	-	19.04
Lock 5		15.51	17.1	Normal pool level	18.65
Lyrup	13.20	14.29	16.1	Below minor flood level	17.54
Berri		13.96	15.5	Below minor flood level	16.50
Lock 4		13.52	-	-	15.90
Loxton	9.80	12.45	13.9	Below minor flood level	15.35
Cobdogla		-	-	-	14.34 (est.)
Lock 3		10.10	-	-	13.99
Overland Corner	6.10	9.78	11.3	Below minor flood level	13.58
Waikerie		-	-	-	12.06
Lock 2		7.92	-	-	11.18
Morgan	3.20	-	-	-	9.62
Lock 1		4.59	3.7	Current date – 24 February	7.54
Swan Reach^	3.58	2.6	6.99		
Walker Flat	-	1.8	5.26		
Mannum PS	1.64	1.2	3.29*		
Murray Bridge	1.34	1.2	2.34*		
Wellington	0.75	1.04	-	-	1.74*
Meningie (Lake Albert)		Varying 0.89 *	1.8	Remain below minor flood level	1.20*
Milang (Lake Alexandrina)		Varying 0.92*	1.3	**	1.40*

Clayton Bay (Lake Alexandrina)		Varying 0.78*	-	-	1.16*
Goolwa & Hindmarsh Island marina (Lake Alexandrina)		Varying 0.54*	1.6	Remain below minor flood level	0.99*

\*Wind and/or tide affected

\*\* There remains a possibility of water levels exceeding the minor flood level for short periods due to weather and/or tide conditions.

^ During the flood event this gauge was modified to be able to measure water levels at higher flows. It has been reinstated to its regular capacity.

Notes

Gigalitre (GL) = 1,000,000,000 litres

mAHD = elevation in metres above Australian Height Datum (approximately equivalent to sea level)

Some things to consider –

- These updated flow and height tables should be used in conjunction with other information sources available at [sa.gov.au/floods](http://sa.gov.au/floods)
- Maps which model potential inundation at various flood levels are available [here](#).
- The locations included in the table have been chosen because they are monitored sites (either current or historical).
- This is the first time in nearly 70 years that River Murray flows have reached many areas of the landscape and it is almost certain that changes to the river channel and floodplain in that time will lead to unforeseen and unexpected difference in flood behaviour. For example, it is possible that the flood this year will look different to pictures you have from the past – even with water flows at similar levels to past events.
- Some of the things that can impact flood behaviour include:
  - Floodplains – Changes on the floodplain will impact how far floodwaters spread, how they soak in and how water returns to the river
  - Bathymetry – Changes to the depth of the river channel due to increased sedimentation or scouring
  - Vegetation – Changes in vegetation density as a result of changes in grazing pressure
  - Infrastructure – New infrastructure like roads, buildings, levees
  - Wind – Wind can cause changes in flood behaviour, especially in the Lower Murray
  - Weather conditions – Rainfall across the border

## Peak water level and flow in SA

While the peak flow has since passed through the length of the River Murray in South Australia water levels remain elevated. In the Lower Lakes water levels may yet rise again as a result of tide and weather conditions.

The adjusted peak flow at the border was around 190 GL/day, taking into account on-ground measurements of flow during this flood event, which aligns with the forecast flow range of 190 – 220 GL/day. The calculated flow at the border continues to fall and today is approximately 42 GL/day at the border and falling quickly. This is a reduction of 149 GL/day since it peaked on 23 December 2022.

A rapid flow recession is occurring throughout South Australia consistent with the recession pattern observed following a number of previous high flow events in the River Murray.

The most recent modelling predicts that the flow at the border will continue to fall and reach approximately 39 GL/day by 24 February 2023. **This is a steep rate of fall and water users should take care and regularly check their boat moorings to make the necessary adjustments.**

Over the last week SA Water have begun reinstating the navigation passes at Locks 3 and 4, following this, the weirs will be slowly reinstated to maintain pool level. Locks 5 and 6 have now returned to normal pool level.

Over the coming weeks the community may notice the ongoing reinstatement of weirs and locks throughout the River Murray in SA when conditions are suitable at each individual lock and weir. Given the rate of recession, it is important to

reinstate the locks and weirs prior to water levels nearing normal pool level (to prevent issues for irrigation offtakes and navigation). Once the infrastructure is back in place, water levels will still be elevated until levels are lowered back to normal pool level. More information will be provided as SA Water reinstates the remaining locks and weirs.

It is important to recognise that even after the river flow has returned to the main channel that many low lying areas of the floodplain will remain inundated for an extended period.

The Department is also closely monitoring salinity levels being experienced in the Lower Darling to determine if elevated salinity levels could occur in South Australia. Salinity at Wentworth on the River Murray is currently around 500 EC. This is within acceptable limits but elevated compared to when the river is within channel. Increased salinity levels are common during flood recessions and DEW will continue to closely monitor the situation.

## Upstream flows

The higher flows experienced in the Darling are now entering the Murray and are not causing a significant rise in water levels at Wentworth. Based on the current forecast, the volume of flow at Wentworth will begin falling in the coming days. Some additional flow is also expected to occur via the Great Darling Anabranch which enters the River Murray downstream of Wentworth. The peak flow down the Anabranch is currently predicted to be around 12 GL/day, noting that travel time for flow in the Anabranch is several weeks longer than the main stem of the Darling River between Menindee Lakes and the Murray. Based on these predictions, the arrival of the Darling River flood peak is forecast to only result in a "flattening" of the flow recession and not a second flood peak in the Murray.

In recent weeks pre-releases have been made from Dartmouth Dam in order to create additional airspace should further rain fall in the catchment in the future. These releases have all been captured in Hume Dam and will not result in additional flow to South Australia.

Hume Dam is currently at 98% capacity and is releasing water to meet downstream orders only, no pre-releases have been required at this stage. Should further rainfall occur then pre-releases may be necessary.

Pre-releases from the upper dams to create airspace does not necessarily equate to an increase in flow at the SA border. There are a number of factors which influence how much water will reach the South Australian border, including how wet or dry the catchments are, how much water is used (and how high demands are), and how full other storages (such as Lake Victoria) between the storage and the border.

## Safety on and around the River Murray in SA

Restrictions for various activities on the River, implemented under the *Emergency Management Act 2004* for users of the River Murray during the flood event, are continuing to be lifted. The latest details of current restrictions can be found here: <https://www.marinesafety.sa.gov.au/river-murray-flood-event-marine-safety-advice>

Whilst water levels continue to recede and areas of the river drop below minor flood levels, the rate of flow, inundation above normal pool level and the period of **high flow** is expected to continue.

Water users are advised to check restrictions for their area prior to accessing the River for any purpose. **Where permitted**, water users should be mindful of the following:

- Operating watercraft and swimming in the main River Murray channel can be more hazardous during high flow. Submerged objects, debris and the force of the current can present a risk to public safety.
- People operating watercraft, swimming, canoeing or participating in other activities on the main River Murray channel are advised to be aware of the risk of high flow, and take precautions to protect life and property.
- When operating a boat on the floodplain or near inundated river banks, be aware of submerged obstacles such as trees and fence lines.
- While swimming, do not jump or dive into the river when you do not know what is below the surface.
- If camping ensure that you are on higher ground away from the river bank.

The following precautions still remain:

- Don't drive, ride or walk through flood-affected causeways or roads.
- Be aware that significant debris is being carried downstream and may pose a hazard to water-based activities.

- The hazards associated with riverbank collapse still exist in some areas so be aware of the signs - such as cracked riverbanks and leaning trees and keep away from fenced or sign-posted affected areas.
- Always wear a personal floatation device on the river.
- Supervise children at all times and do not allow them to play in or near fast-flowing river water.
- If in doubt, stay out.
- Listen and take action on any instructions from the emergency services - the SASES, SA Police and the CFS.
- Tune to ABC local radio for community safety information.

**Requests for assistance for on-water incidents or inundation of property should be directed to the SA State Emergency Service (SASES) on 132 500.**

**For life threatening emergencies call 000.**

## Changing water levels

River users should be aware that water levels can change quickly. All river users, houseboat owners and operators, as well as irrigators, will need to regularly check water levels and make daily adjustments.

## Lake Bonney & salinity

Irrigators who take water from the main River Murray channel between Lake Bonney and Lock 2 should be aware that salinity levels have increased from around 300 EC (electrical conductivity) to over 900 EC in the last week and are likely to continue increasing. On Thursday, 16 February the reading at Lock 3 was 984 EC - by comparison Lock 2 was 570 EC and Lock 4 was 435 EC.

The increased salinity level is in response to the re-opening of the inlet to Lake Bonney. As the water enters the main channel from the Lake a brief increase in salinity levels is occurring in the river downstream of the lake. Modelling undertaken by the Department for Environment and Water (DEW) has indicated that further rises are still possible depending on how quickly water levels fall at Lock 3.

This is common during flood recessions and is a result of the normally higher salinity water held in Lake Bonney being drawn into the river with falling water levels. There are a number of factors which influence the volume and timing of saltier water entering the main river channel, including the amount of mixing that occurs between fresher and saltier water within Lake Bonney upon re-opening, and the actual rate at which water levels fall in the river compared to what has been predicted.

Downstream irrigators are encouraged to monitor the [daily salinity levels](#) provided by SA Water as part of their business operations.

## Barrage operations and water levels in the Lower Lakes

The water level in Lake Alexandrina is approximately 0.91 m AHD and Lake Albert is approximately 0.90 m AHD.

As of Tuesday 14 February 2023 SA Water began the process of closing sections of the 570 operational bays at the barrages, following their opening throughout the River Murray floods. All operational gates across all 5 barrages were opened from 2 December 2022 up until this week to pass the floodwaters, even during storm events. Fishways at all barrages and at Hunters Creek (11 in total) also remained open to provide fish passage between the Coorong and Lower Lakes.

As floodwaters continue to recede in the coming weeks, more barrage gates will be gradually reinstated in order to maintain an appropriate water level in the Lower Lakes for this time of year. More information will be provided as it becomes available.

Barrage releases are normally calculated using water levels from upstream and downstream of the barrages which are entered into equations to determine the volume of flow through each of the five barrages and the fishways. The existing methodology for calculating barrage releases is not accurate with the very high flow and water levels currently being experienced. Analysis will be undertaken following the flood event to develop a flow record of barrage releases throughout the flood.

With a large number of barrage gates remaining open, landholders and communities in the Lake Alexandrina region, particularly between Loveday Bay and Narrung Peninsula and in the vicinity of Goolwa, Hindmarsh Island and Mundoo Islands, are advised that short-term salinity increases are possible over the next few weeks due to flood-related barrage operations. With the small chance that saltier water will enter Lake Alexandrina for short periods from high tides or storms, residents pumping water from the Lower Lakes are advised to check real-time salinity data here:

<https://water.data.sa.gov.au/>

It is also possible that wind, tide and wave action may temporarily result in higher levels in some locations. This local weather based variation is consistent with the variation seen on the Lakes outside of the current event.

Water levels and barrage operations are monitored closely by the South Australian Government, Murray-Darling Basin Authority and Commonwealth Environmental Water Office.

## Murray Mouth

Bathymetric survey of the width and depth of the Murray mouth has shown that the mouth is continuing to scour as a result of the high flows, which will assist in increasing the volume of water that is able to be released from the barrages. A wider and deeper Murray Mouth will have positive environmental benefits following the flood through enabling better exchange of water between the ocean and the Murray estuary and Coorong.

## River Murray River Vessel Waste Disposal Stations

All remain offline with the exception of Goolwa which remains operational.

These proactive and preventative measures were required to minimise risks to public safety and water quality and ensure infrastructure is protected.

As water levels recede, DEW will recommission each disposal station when it is deemed safe and possible to do so. The process to recommission includes regaining safe access to the site, inspecting the infrastructure for any damage, repairing any damaged infrastructure, reinstating equipment, and the reconnection and testing of services.

Until the river vessel waste disposal stations can be recommissioned, commercial options remain available for businesses to utilise temporarily at houseboat owners and operators' expense while the disposal stations are closed.

If you have any questions, please contact the DEW Engagement Team on [DEW.WIOCommunications@sa.gov.au](mailto:DEW.WIOCommunications@sa.gov.au)

## Levee embankments

Engaged levee banks along the Lower Murray from Mannum to Wellington remain closed in accordance with [Emergency Services \(River Murray\) \(No 4\) Direction 2023](#) which came into effect at 11:00 pm Wednesday 15 February 2023.

Drone inspections of Government owned levee embankments are being undertaken regularly to monitor how the levees are engaged by the receding flood waters. On ground inspections will be undertaken once deemed safe to do so.

Any Local Irrigation Trust members and contractors still accessing the levees for emergency response or maintenance works are encouraged to take all necessary precautions when working on the levees, particularly during or following wet weather.

If you have any questions, contact the DEW Engagement Team on [DEW.WIOCommunications@sa.gov.au](mailto:DEW.WIOCommunications@sa.gov.au)

## Environmental news

Unregulated flows have been continuous to SA since July 2021 due to wetter than average conditions across much of the Murray-Darling Basin. Apart from small volumes that are delivered as part of SA's entitlement flow or to help manage blackwater from time to time, deliveries of water for the environment are generally on hold until flooding recedes. High flows provide a range of benefits for the environment in SA, including:

- connecting the river with floodplains and wetlands, inundating areas that have been dry for many years;
- allowing fish dispersal and movement into new habitats and throughout the Murray-Darling Basin;

- providing 'flowing water habitat' to benefit native fish, animals, and plants in the River Murray channel that have adapted to a riverine environment, including supporting spawning and recruitment of large native fish. Golden perch have been detected spawning in the South Australian Murray in recent weeks;
- improving water quality and productivity in the Coorong, providing a food-rich environment for fish and birds including healthy populations of keystone native plant *Ruppia tuberosa*;
- providing habitat for birds, frogs and threatened small-bodied native fish species in the Lower Lakes;
- removing excess salt from the River Murray.

## Blackwater

Blackwater occurs naturally when floods wash leaves, grass and cropping material off riverbanks and floodplains into waterways. High levels of organic matter in waterways, combined with warm weather, can cause oxygen levels in the water to drop. This is known as hypoxic (low oxygen) blackwater, which can have a blackish colour and a strong, unpleasant smell.

There is currently no hypoxic blackwater present in the South Australian section of the River Murray.

PIRSA, with support from DEW, SA Water and the Murray-Darling Basin Authority and other relevant government agencies, continues to closely monitor blackwater events upstream and plan mitigation measures should it reach South Australia.

When dissolved oxygen levels in water drop below critical levels, it can cause fish and crustaceans to die. To report sightings of large numbers of dead or distressed fish, please contact the 24-hour Fishwatch hotline on 1800 065 522.

Water quality alerts issued by SA Health to inform the community about water quality safety for domestic use and recreational activities can be found at this website:

<https://www.sahealth.sa.gov.au/wps/wcm/connect/public+content/sa+health+internet/public+health/water+quality/water+quality+alerts>

## Further information

All information regarding the 2022/23 River Murray flood event and information on recovery, relief and financial assistance (including that of partner agencies) can be accessed via the following link: <http://www.sa.gov.au/topics/emergencies-and-safety/river-murray-flood>.

Information for flood recovery can be accessed at <https://www.sa.gov.au/topics/emergencies-and-safety/river-murray-flood/recovery>

The Water Data SA website is South Australia's comprehensive water information portal. For real-time data (like salinity, water levels) go to the following page: [Water Data SA](#). Please note that some surface water monitoring stations were removed as river flow increased and that data will be unavailable for those stations until they are reinstated.

Up-to-date River Murray salinity, flow and water level information can also be accessed at the SA Water and Murray-Darling Basin Authority websites:

- [SA Water River Murray info - levels, flows etc.](#)
- [Murray-Darling Basin real-time water data](#)

The latest news, information and announcements about the River Murray and Basin Plan are available at [River Murray Update](#).

Details of river height and rainfall information in the River Murray within Victoria and New South Wales are available at the Bureau of Meteorology website:

- [Victoria rainfall and river conditions](#)
- [NSW rainfall and river conditions](#)

Department for Environment and Water [Home page](#).

OFFICIAL

Classification	Public I2 A2
Issued	17 February 2023
Authority	DEW
Master Document Location	R:\Water Group\RMO\WRO\04 Communications\Flow Advices\2022-23
Managed and Maintained by	Water Infrastructure and Operations Branch
Author	Water Infrastructure and Operations Branch
Reviewer	Director, Water Infrastructure and Operations